



Service & Support Inspection & Reinstatement Policy - 990222 January, 2012

Juniper Networks, Inc. requires that when (i) the standard warranty has ended, (ii) a previously purchased contract has expired or (iii) there has been a transfer of product ownership, the Juniper Networks, Inc. equipment must be inspected or a reinstatement fee paid before placing such equipment under a new support services contract. The inspection and reinstatement fee is non-refundable and does not apply to the purchase of the support services contract.

Juniper Networks, Inc. requires that when a support services contract has lapsed for a period of less than one (1) year, a new contract that is retroactive to the day following the end of the expired contract is required. Juniper does not require that the equipment be inspected or a reinstatement fee paid. The equipment is eligible for any active support services contract found on the current price list, subject to regional availability.

An inspection or reinstatement fee is required for equipment for which the support services contract has lapsed for a period of more than one (1) year. The equipment is eligible for any active support service contract found on the current price list, subject to regional availability. The new contract will begin the day the order is processed.

Juniper Networks, Inc. requires an inspection or a reinstatement fee for all products that were not originally purchased, by the then current owner of the equipment, from Juniper or an Authorized Juniper Partner. Additionally, Juniper Networks, Inc. software is only licensed to the original purchaser and the license is not transferable.

A re-registration fee is required to allow the legal use of the Juniper Networks, Inc. software. Please check re-registration fee pricing on the current Juniper Networks, Inc. Global Price List. The combination of the inspection or reinstatement fee with the re-registration fee will allow the equipment to be eligible for a support services contract and to receive support from Juniper Networks, Inc.

The product inspection is conducted to check that the equipment has been maintained in adherence to the support services procedures detailed in the product technical documentation supplied with the equipment upon initial sale and the software installed is a currently supported release. All equipment must be inspected and deemed to be in good operating condition before it will be eligible for coverage on a Juniper Networks, Inc. Support Services contract. Products that require inspection include: T-series; M-series; MX-series; ERX-series; SRX; NetScreen FW/VPN Systems (e.g. 500, 2000, 5000 series); EX 8200; and NetScreen Secure Access 3000/4000/5000/6000 series. Please check inspection fee pricing on the current Juniper Networks, Inc. Global Price List.

Products that do not require an inspection include: EX 3200/4200; J-series; SSG; NetScreen Access 1000/2000 series; NetScreen FW/VPN Appliances (e.g. 5, 25, 50, 200); NetScreen RA500/SA700; DX-series; WX-series; VF-series; NSMXpress; and STRM series. These appliance type units are less complex than the system level equipment and require a reinstatement fee. The reinstatement fee is equal to one (1) year of the then current CorePlus support for the specific product.

Equipment that has not been inspected or for which a reinstatement fee has not been processed will be eligible for time and material level of support only at then current rates, and will be subject to minimum charges.

Products that have reached End of Support (EOS) or are within one (1) year of EOS are not eligible for the purchase of a support services contract. Equipment that has reached the End of Life (EOL) announcement date will have services available reduced during the five (5) year EOS timeline. Please check services availability on the current Juniper Networks, Inc. Global Price List

Prior to scheduling a product inspection, Juniper Networks, Inc. will require that customers provide the following: (a) an inventory of hardware and software; (b) origin of equipment; (c) serial numbers of all Field Replacement Units (FRU), such as chassis, Physical Interface Cards (PIC), Flexible PIC Concentrators (FPC), and line cards; (e) a purchase order for

inspection and software re-license; and (f) suitable location to properly test the equipment. Additionally, all possible cards must be installed in the chassis to be inspected and the equipment must be powered up prior to an engineer arriving to perform the inspection.

Inspection fees will be charged at then current published rates, and will be subject to minimum charges. Inspection fees include: (a) labor required to perform inspection; (b) visual inspection of complete system including all FPCs, line cards and PICs; (c) verification of installation of any mandatory engineering changes; (d) collection and verification of serial numbers; (e) system power up and operation of network interfaces; (f) verification of operating software revision, and (g) normal travel expenses within the region. Please note that any replacement of defective hardware, update or upgrade of software, and software license fees are not included as part of the inspection process. Contact the renewal team (renewals@juniper-service.net) or your regional Service Business Manager with any questions on Product Inspection and Reinstatement fee.

Corporate and Sales Headquarters

Juniper Networks, Inc.
1194 North Mathilda Avenue
Sunnyvale, CA 94089 USA
Phone: 888.JUNIPER (888.586.4737)
or 408.745.2000
Fax: 408.745.2100

APAC Headquarters

Juniper Networks (Hong Kong)
26/F, Cityplaza One
1111 King's Road
Taikoo Shing, Hong Kong
Phone: 852.2332.3636
Fax: 852.2574.7803

EMEA Headquarters

Juniper Networks Ireland
Airsides Business Park
Swords, County Dublin, Ireland
Phone: 35.31.8903.600
EMEA Sales: 00800.4586.4737
Fax: 35.31.8903.601

Copyright 2012 Juniper Networks, Inc. All rights reserved. Juniper Networks, the Juniper Networks logo, Junos, NetScreen, and ScreenOS are registered trademarks of Juniper Networks, Inc. in the United States and other countries. All other trademarks, service marks, registered marks, or registered service marks are the property of their respective owners. Juniper Networks assumes no responsibility for any inaccuracies in this document. Juniper Networks reserves the right to change, modify, transfer, or otherwise revise this publication without notice.